STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155712	A. BUILDING **01, 02** B. WING _____	R **04/21/2015**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
COVERED BRIDGE HEALTH CAMPUS	**1675 W TIPTON ST** **SEYMOUR, IN 47274**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/20/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 04/21/15 Facility Number: 003342 Provider Number: 155712 AIM Number: 200403740 At this PSR survey, Covered Bridge Health Campus was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies, and 410 IAC 16.2. The original building was surveyed with Chapter 19, Existing Health Care Occupancies. This one story facility was determined to be of Type V (111) construction and fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, spaces open to the corridors, and hard wired smoke detectors in all resident sleeping rooms. The healthcare portion of the facility has a capacity of 68 and had a census of 64 at the time of this visit. All areas where residents have customary access were sprinkled and all areas providing facility services were sprinkled.	{K 000}		
{K 000}	INITIAL COMMENTS	{K 000}		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155712	A. BUILDING **01, 02** B. WING _____	R **04/21/2015**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
COVERED BRIDGE HEALTH CAMPUS	**1675 W TIPTON ST** **SEYMOUR, IN 47274**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 1 A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 02/20/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 04/21/15 Facility Number: 003342 Provider Number: 155712 AIM Number: 200403740 At this PSR survey, Covered Bridge Health Campus was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), and 410 IAC 16.2. The 2005 300 Hall four resident room addition was surveyed with Chapter 18, New Health Care Occupancies. The 300 Hall addition is a fully sprinkled one story addition of Type V (111) construction. The 300 Hall addition has a fire alarm system with smoke detection in the corridors, spaces open to the corridors, and hard wired smoke detectors in all resident sleeping rooms. The healthcare portion of the facility has a capacity of 68 and had a census of 64 at the time of this survey. All areas where residents have customary access were sprinkled and all areas providing facility services were sprinkled.	{K 000}		